


Offset Taper Layout



1. Draw line down left side notebook paper
 2. Take circumference of butt and mark it out from line on left hand side this will be A to B
 3. Use A to B measurement to estimate number of patterns to show (in this case 5)
 4. Count down 4 lines this will be I to J
 5. Take circumference of tip and mark it on 4th line down (I to J)
 6. Draw line from point B to point J
 7. Take measurement I to J and mark it at the Butt end
 8. Then G to H, E to F, C to D and A to B
- NOTE: 1. remember to take only half of I to J for 180 degree marks