



Leap Year Data format with Nortel Phase 2 IP Sets Show incorrect Date

Notice:

This bulletin replaces bulletin 2008008659.1. This update has been issued to communicate some new information regarding the issue.

BULLETIN ID: 2008008659, Rev 2
PUBLISHED: 2008-02-28
STATUS: Active
REGION: APAC
CALA
EMEA
GC
NA
PRIORITY: Major
TYPE: Bulletin

Reissue Reason:

Update

Background:

An issue has been identified with Nortel Phase 2 IP Sets where the Date can be incorrectly displayed on Feb 29th for Leap Year.

Analysis:

IP Phase 2 sets will have a display issue of the Date Feb 29. The display of the IP Set will incorrectly display the Date for Feb 29th. When the date should display Feb 29 the display has shown to display either March 1 or February 28. There is no other operational issues identified with the IP Sets functionality other than the data display.

Phase 1 IP Sets and TDM phones have not experienced any issues with the display of Feb 29.

Recommendations:

Do not attempt to restart the phone or change the date on the system as presently there is no corrective action available to have the date display correctly for Feb 29.

Required Actions:

Once the date changes to March 1st the IP Set will need to be taken off-hook and placed back on-Hook for the Date to be updated. If the display is not already updated correctly, after March 1st.

Attachments:

There are no attachments for this bulletin

Products and Releases:

The information in this bulletin is intended to be used with the following products and associated releases:

PRODUCT	RELEASE
Phones & Accessories-IP-IP Phone 1110	
Phones & Accessories-IP-IP Phone 1120E	
Phones & Accessories-IP-IP Phone 1140E	
Phones & Accessories-IP-IP Phone 1150E	

Phones & Accessories-IP-IP Phone 2002	
Phones & Accessories-IP-IP Phone 2004	
Phones & Accessories-IP-IP Phone 2007	

To view the most recent version of this bulletin, access technical documentation, search our knowledge base, or to contact a Technical Support Representative, please visit Nortel Technical Support on the web at: <http://support.nortel.com/>. You may also sign up to receive automatic email alerts when new bulletins are published.

**REFERENCE:
PRE-REQUIRED PATCH:
PATCH ID:**

Copyright 2007 Nortel Networks. All rights reserved. Information in this document is subject to change without notice. Nortel assumes no responsibility for any errors that may appear in this document. The information in this document is proprietary to Nortel Networks.

Nortel recommends any maintenance activities, such as those outlined in this bulletin, be completed during a local maintenance window.

Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks. All other trademarks are the property of their respective owners.